



A-B-C

Always be careful.

- The **leading cause of fatalities** for workers in work zones is **being run over or backed over**
- Sensors and cameras are meant to assist drivers, not replace them; **you are your car's best safety feature**
- Get out of your car – **do a 360-degree walk-around**
- Once behind the wheel, be sure to **look over your shoulder**
- If possible, **get help from a spotter**

**I Didn't Think
I Didn't See
I Didn't Know**

- Backing up accounts for less than **1%** of a driver's time behind the wheel but regularly accounts **25%** of collisions
- When it comes to backing, safety starts with a **G-O-A-L ... Get Out and Look**

